

CONSTRUCTION - PLUMBING



MOST CITED STANDARDS FOR CONSTRUCTION - PLUMBING JANUARY 1, 2001 TO DECEMBER 31, 2001

RANK	STANDARDS CITED		NUMBER
1	1926.404	Ground fault circuit interrupters were not used. Conductors and equipment were not protected from overcurrent in accordance with their ability to safely conduct current.	3
2	80-7	The general requirements for mechanical power presses were not met.	2
2	1910.1200(e)	Employers did not develop and implement a written hazard communication program for their work places.	2
2	1926.250	The general requirements for the storage of materials were not met.	2
2	1926.350(a)	Requirements for transporting, moving, and storing compressed gas cylinders were not met.	2
2	1926.405(b)	Conductors entering boxes, cabinets, or fittings were not protected from abrasion, and openings through which conductors entered were not effectively closed . All pull boxes, junction boxes, and fittings were not provided with covers approved for the purpose.	2
2	1926.503	A training program was not provided for employees who might be exposed to fall hazards . A written certification record was not provided by the employer.	2